

## Andrew Barclay, Kilmarnock - Locomotive Works Lists

### 2300 – 2399

No	Desp date	Type	Cyls (ins)	DW ft/ins	Gauge	Owner when new	Number/Name
2300	25.12.50	0-4-0WT	OC 8½x12		Metre	Parry & Co Ltd, Madras for East India Distilleries & Sugar Estates Ltd, Nellikuppam Sugar Factory\	E I D & S F LTD
2301	8.10.51	0-4-0ST	OC 16x24	3'7	Std	ICI Ltd, London for Gaskell Deacon Works, Widnes	MUSPRATT
2302	24.5.51	0-4-0WT	OC 7x11		2'0	Parry & Co Ltd, London for Central Provinces Manganese Ore Co Ltd, Kandri mine, India	C P M O CO LTD
2303	16.11.50	0-6-0ST	OC 16x24	3'7	5'6	Nixon, Forest & Co, London for Associated Cement Companies Ltd, Damodar Cement Works, India	A C C LTD
2304	24.4.51	0-4-0ST	OC 16x24	3'7	Std	B E A, London for Keadby Power Station, Lincs	B E A No 1
2305	13.6.51	0-4-0ST	OC 16x24	3'7	Std	B E A, London for Keadby Power Station, Lincs	B E A No 2
2306	16.7.51	0-6-0ST	OC 15x22	3'5	Std	Stanton Ironworks Co Ltd, near Nottingham (sent to Stewarts & Lloyds Minerals Ltd, Woolsthorpe Quarries, Leics.)	DENTON
2307	18.9.51	0-4-0ST	OC 14x22	3'5	Std	Mitchells & Butlers Ltd, Cape Hill Brewery, Birmingham	JOHN BARLEYCORN
2308	3.4.51	0-4-0ST	OC 17x24		Std	ICI Ltd, London for Castner-Kellner Works, Runcorn	No 7
2309	6.4.51	0-4-0ST	OC 17x24		Std	ICI Ltd, London for Castner-Kellner Works, Runcorn	No 8
2310	31.5.51	0-4-0ST	OC 17x24		Std	ICI Ltd, London for Castner-Kellner Works, Runcorn	No 9
2311	12.2.51	0-4-0ST	OC 14x22	3'5	Std	Hadfields Ltd, East Hecla Works, Sheffield	No 14933
2312	20.2.51	0-4-0ST	OC 16x24	3'7	Std	Hadfields Ltd, East Hecla Works, Sheffield	No 14932
2313	6.6.51	0-6-0ST	OC 15x22	3'5	Std	Stewarts & Lloyds Ltd, Corby (sent to Buckminster Quarries, Lincs),	STAINBY
2314	17.7.51	0-6-0ST	OC 15x22	3'5	Std	Stewarts & Lloyds Ltd, Corby (sent to Buckminster Quarries, Lincs),	SEWSTERN
2315	22.10.51	0-4-0ST	OC 14x22	3'5	Std	B E A, London for Braehead Power Station, Renfrew	BRAEHEAD No 1
2316	22.11.51	0-4-0ST	OC 14x22	3'5	Std	B E A, London for Braehead Power Station, Renfrew	BRAEHEAD No 2
2317	20.3.50	0-4-0ST	OC 14x22	3'5	Std	NCB, Durham for Stella Gill Coke Works	502
2318	15.1.52	2-8-4T	OC 14x18		2'6	Parry & Co Ltd, Calcutta for Equitable Coal Co, Balidaha, India	E S R 4
2319	24.1.52	2-8-4T	OC 14x18		2'6	Parry & Co Ltd, Calcutta for Equitable Coal Co, Balidaha, India	E S R 5
2320	7.1.52	0-4-0ST	OC 14x22	3'5	Std	NCB, Darlington for East Hetton Colliery	No 54
2321	21.1.52	0-4-0ST	OC 14x22	3'5	Std	NCB, Darlington for Trimdon Grange Colliery	No 55
2322	17.3.52	0-4-0ST	OC 14x22	3'5	Std	NCB, Darlington for Bowburn Colliery	No 56
2323	25.2.52	0-4-0ST	OC 16x24	3'7	Std	Dorman Long & Co Ltd, Middlesbrough for Lackenby Works	No 6
2324	3.3.52	0-4-0ST	OC 16x24	3'7	Std	Dorman Long & Co Ltd, Middlesbrough for Lackenby Works	No 7
2325	6.6.52	0-4-0ST	OC 16x24	3'7	Std	BEA for Clyde's Mill Power Station, Glasgow	No 6
2326	30.6.52	0-4-0F	OC 16x18	3'0	Std	British Enka Ltd, Aintree, Liverpool	
2327	8.5.52	0-4-0ST	OC 16x24	3'7	Std	BEA, London for Chadderton Power Station, Oldham	CHADDERTON No 1

## Andrew Barclay, Kilmarnock - Locomotive Works Lists

2328	29.10.52	0-4-0F	OC 19x22	3'5	Std	Dorman Long & Co Ltd, Middlesbrough for LackenbyWorks	No 8
2329	29.9.52	0-6-0F	OC 21x22	3'5	Std	Dorman Long & Co Ltd, Middlesbrough for Lackenby Works	No 9
2330	25.3.53	0-6-2T	OC 12½x18	3'0	3'6	Wm & Jno Lockett Ltd, Liverpool for Hacienda San Jacinto, Peru	SANTA ROSA
2331	27.11.52	0-6-0ST	OC 17x24	3'7	Std	NCB, Abercarn for Blaenserchan Colliery, near Pontypool	ILLTYD
2332	16.12.52	0-6-0ST	OC 17x24	3'7	Std	NCB, Abercarn for Tirpentwys Colliery, Pontypool	ISLWYN
2333	22.1.53	0-4-0ST	OC 16x24	3'8	Std	Millom & Askam Hematite Iron Co Ltd, Cumberland	No 1
2334	4.3.53	0-4-0ST	OC 16x24	3'8	Std	Millom & Askam Hematite Iron Co Ltd, Cumberland	No 2
2335	5.10.53	0-6-0T	OC 18x24	3'10	Std	NCB, for Central Workshops, Waterside, Ayr	No 8
2336	6.3.53	0-6-0ST	OC 16x24	3'7	5'6	Associated Cement Co Ltd, Bombay for Kymore works, India	
2337	27.5.53	0-6-0ST	OC 16x24	3'7	5'6	Associated Cement Co Ltd, Bombay for Lakheri works, India	
2338	11.6.53	0-6-0ST	OC 16x24	3'7	5'6	Associated Cement Co Ltd, Bombay for Chaibasa works, India	
2339	17.9.53	0-6-0ST	OC 16x24	3'7	Std	NCB, Aberdare for Deep Navigation Colliery, Treharris	No 2
2340	14.12.53	0-6-0T	OC 18x24	4'0	Std	NCB (sent to Aberaman Engineering Works, Mountain Ash)	
2341	5.5.53	0-4-0ST	OC 14x22	3'5	Std	NCB, Darlington for Thrislington Colliery	
2342	10.2.54	0-6-0F	OC 17x18	3'0	3'6	Blane & Co, Johannesburg for South African Pulp & Paper Industries Ltd, Tugela works	
2343	8.4.53	0-4-0ST	OC 10x18	3'0	Std	Thomas McGhie & Sons, Thistle Plaster Works, Penrith	
2344	17.3.54	0-6-0ST	OC 15x22	3'5	Std	NCB, Nottingham for Clifton Colliery	No 3
2345	14.7.53	0-4-0ST	OC 14x22		Std	Pilkington Bros Ltd, Barnby Dun, near Doncaster	DONCASTER
2346	11.5.54	0-6-0	OC 16x24	3'7	5'6	Associated Cement Companies Ltd, Bombay for Sevaliya works	A C C LTD
2347	19.3.54	0-6-0	OC 16x24	3'7	5'6	Associated Cement Companies Ltd, Bombay for Lakheri works	A C C LTD
2348	8.4.54	0-6-0	OC 16x24	3'7	5'6	Associated Cement Companies Ltd, Bombay for Chaibasa works	A C C LTD
2349	3.3.54	0-4-0F	OC 15x18	3'0	Std	Richard Thomas & Baldwins Ltd, Redbourn Works, Scunthorpe	
2350	11.1.54	0-6-0ST	OC 15x22	3'5	Std	Stewarts & Lloyds Ltd, Corby for Woolsthorpe Quarries, Leics	BELVOIR
2351	25.1.54	0-6-0ST	OC 15x22	3'5	Std	Stewarts & Lloyds Ltd, Corby for James Pain Ltd, Market Overton Quarries, Rutland	RUTLAND
2352	1.7.54	0-4-0ST	OC 14x22	3'5	Std	BEA, London for Goldington Power Station, Beds	E D 8
2353	6.9.54	0-4-0ST	OC 14x22	3'5	Std	BEA, London for Tilbury Power Station, Essex	E D 9
2354	23.9.54	0-4-0ST	OC 14x22	3'5	Std	BEA, London for Goldington Power Station., Beds	E D 10
2355	20.10.54	2-8-4T	OC 14x18		2'6	Duncan McNeil & Co Ltd, London for Equitable Coal Co, Balidaha, India	E S R 6
2356	22.12.54	2-8-4T	OC 14x18		2'6	Duncan McNeil & Co Ltd, London for Equitable Coal Co, Balidaha, India	E S R 7
2357	20.4.55	0-4-0ST	OC 16x24	3'7	Std	NCB, Fife for Lochhead Colliery	No 20
2358	29.11.54	0-6-0ST	OC 16x24	3'7	Std	NCB Lothians for Niddrie workshops	No 11
2359	27.10.54	0-6-0ST	OC 14x22	3'5	Std	NCB, Aberdare for Penrikyber Colliery, Glamorgan	No 1

## Andrew Barclay, Kilmarnock - Locomotive Works Lists

2360	9.12.54	0-4-0ST	OC 14½x22	3'5	Std	BEA, Leeds for Ferrybridge B Power Station	No 3
2361	8.6.54	0-4-0ST	OC 14x22	3'5	Std	Long Meg Plaster & Mineral Co Ltd, Cocklakes, Carlisle for Long Meg Gypsum Mines, Lazonby	W S T
2362	16.3.55	0-4-0ST	OC 16x24	3'7	Std	NCB, Longbenton for Bedlington F Colliery	
2363	21.3.55	0-4-0T	OC 13½x20		Metre	Tata Ltd, London for Jamshedpur Works, India	T I S CO LTD
2364	19.4.55	0-4-0T	OC 13½x20		Metre	Tata Ltd, London for Jamshedpur Works, India	T I S CO LTD
2365	15.2.55	0-4-0ST	OC 14x22	3'5	Std	Richard Thomas & Baldwins Ltd, Irthlingborough for Blisworth Quarries, Northants	BLISWORTH No 1
2366	7.2.55	0-4-0ST	OC 14x22	3'5	Std	NCB, Nottingham for Pye Hill Colliery, Pye Bridge [dwarfed loco]	No 19
2367	21.6.55	0-4-0ST	OC 16x24	3'7	Std	BEA, London for Chadderton Power Station, Oldham	CHADDERTON No 2
2368	3.2.55	0-4-0ST	OC 16x24	3'7	Std	NCB, Ayr for Lugar, Cumnock	
2369	5.5.55	0-4-0ST	OC 16x24	3'7	Std	NCB, Ayr for Bank Colliery, New Cumnock	
2370	10.5.55	0-4-0ST	OC 14x22	3'5	Std	Scottish Gas Board, Provan Works, Glasgow	No 1
2371	2.11.55	0-6-0ST	OC 16x24	3'7	Std	NCB, Aberdare for Taff Merthyr colliery, Treharris	
2372						[cancelled order]	
2373	17.4.56	0-4-0F	OC 15x18	3'0	Std	Imperial Paper Mills Ltd, Gravesend	IMPERIAL No 1
2374	10.12.56	0-4-0ST	IC 10x15	2'9	Std	Llanelly Steel Co (1907) Ltd, Llanelly	CHRISTOPHER
2375	19.12.58	0-6-0T	OC 10¾x14		2'6	Parry & Co Ltd for Daurala Sugar Works, India	D S T ASHOKA
2376	24.12.61	0-4-0F	OC 19x22	3'5	Std	Dorman Long (Steel) Ltd, Middlesbrough for Lackenby works	No 10
2377	27.9.62	0-6-2	OC 10x12	2'0	700mm	Robert Stephenson & Hawthorns Ltd, Darlington for Railway Mine and Plantation Equipment Ltd (sent to PNP, Majang Palm Oil Estate, Sciantar, Sumatra) [built to a Bagnall specification]	

### Notes

In this period there are a number of discrepancies in different company sources in relation to despatch dates.

In a number of cases (especially NCB) the locations given in the original records were not the location the locos were despatched to; they have been corrected in this list.